

LAMPIRAN



Gambar 4.3 Kondisi Di Lapangan Penelitian



Gambar 4.1 Ujung Tiang Pondasi Dilapangan Proyek


2.4.3 Hasil analisis penelitian

PT. GEO STRUKTUR INDONESIA
23 - 12 PIT PEMB JEMBA TA N JONDUL

23/12/2020

D:\...023-12 PIT PEMB JEMBATAN JONDUL\23-12 PIT PEMB JEMBATAN JONDUL.PIT

PIT-W 2009 - 2



Gambar 4.2 Hasil Analisa Rambatan Gelombang Pada Penelitian Tiang Pondasi